



# 2017 Kia Niro Headlight Replacement

This is a guide for replacing a broken or faulty 2007 Kia Niro headlight.

Written By: Sydney Harper



## INTRODUCTION

This guide gives step-by-step instructions to replace the XtraVision Fog Light/Headlight Bulb 9005XV-2 in a 2017 Kia Niro. Fog Light/Headlight bulb usually burns out after 1000 hours and it needs to be replaced but some others last for 30000 hours. When replacing Fog Light/Headlight Bulb 9005XV-2 in a 2017 Kia Niro, Fog Light/Headlight Bulb should be changed in pairs. For safety concerns, Bulbs should be changed before they burned out because driving without functioning bulbs can be dangerous at night.



### PARTS:

- [XtraVision Fog Light/Headlight Bulb 9005XV-2](#) (1)



## Step 1 — Headlight



- Open the hood of the vehicle and make sure it is secured to prevent injury.

## Step 2



- Locate the bulb cover cap which can be found under the hood and directly behind the headlight.

### Step 3



- Remove the bulb cover cap by rotating it counter-clockwise until it is fully detached.

### Step 4



- Place the cap in a location that is out of the way of your work area and where you can easily find it.



## Step 5



- Remove the old bulb by rotating counter-clockwise until it is detached, being careful not to drop the bulb into the hood of the vehicle.

## Step 6



- Prepare your replacement XtraVision Fog Light/Headlight Bulb 9005XV-2 for installation by removing it from the packaging and ensuring that the bulb is not broken.

## Step 7



- Insert the new bulb by pushing it into the bulb compartment.
- Turn the bulb clockwise until it is secure.

## Step 8



- Reattach the cap you previously set aside by rotating clockwise until secure.