




# Beats Solo 3 Charging Port Replacement

This is a charging port replacement guide for...

Written By: Abdulaziz Alotaibi



# INTRODUCTION

This is a charging port replacement guide for the Beats Solo 3 Headphones, Model number A1796. Symptoms that suggest the need for a charging port replacement can be found on our [troubleshooting page](#).



## TOOLS:

- [Phillips #00 Screwdriver](#) (1)
  - [Metal Spudger](#) (1)
  - [Tweezers](#) (1)
  - [Soldering Workstation](#) (1)
-

## Step 1 — Charging Port



- Use a nylon or metal spudger to carefully remove the ear pad from the right ear cup.


⚠ Be careful to not rip the ear pad fabric with your tools.

## Step 2




- Use a Phillips #00 screwdriver to remove the seven screws that hold the speaker in place.
- ⓘ There are two screws in the big red circle at the bottom.

## Step 3



- Desolder all wires connecting the circuit panel to the rest of the device.
- ⓘ There are two wires in the big red circle at the bottom and one in the small red circle above.

## Step 4



- After you desolder all wires you are able to remove and replace the charging port.

To reassemble your device, follow these instructions in reverse order.